



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Reviewed *PAT*

Report Date: **09/08/2014**

Mine Name: Tusher Redwood	Permit Number: S/019/0061	Mine Status: Reclaimed
Operator Name: Larry Walker	Inspection Date: 08/27/2014	Permit Fees: No Fee Req.
Inspector(s): M. Bradley	Inspection Time: 9:00am	Bond Amount: \$1,000
Attendee(s): Doug Rowles, BLM	Weather: Cloudy, mild	Bond Escalation: N/A
Inspection Purpose: Operator requested bond release		Prior Inspection: 05/06/2014

Conclusions and Recommendations

Location: 607527.00 m E, 4285532.00 m N, UTM Zone 12N. Went back to site with Doug Rowles, BLM, to attempt to backfill hole created by rock club on previously graded site. Upon arrival, hole was full of water from recent rains. Backfilled hole as best we could with soil and rocks. We couldn't see the back cavity, but we believe we were able to backfill it to the point where it would take some work for someone to reopen it and the potential safety hazards were alleviated. According to the accepted NOI, revegetation standards were minimal as little to no vegetation existed prior to disturbance. With concurrence from BLM, recommend releasing remainder of bond.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Backfilled hole dug by a club of rock collectors		
3. <i>Protection of Drainages/Erosion Control</i>	<input type="checkbox"/>	<input type="checkbox"/>
4. <i>Deleterious Material</i>	<input type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input type="checkbox"/>	<input type="checkbox"/>
6. <i>Reclamation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Site was previously regraded.		
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
See Item 2 above		
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Minimal standards required as per accepted NOI. Volunteer vegetation from local sources.		
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: *Michael P. Bradley*

CC: Doug Rowles, BLM (drowles@blm.gov); Larry Walker, PO Box 25, Moab, Utah, 84532-0025

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M019-Grand/S0190061-TusherRedwood/inspections/INSP-08272014.pdf





Hole as seen in May, 2014



Hole as found on August 27, 2014. Full of water from recent rains.



Hole after backfilling with excavated material and rocks



Rest of Cast Claim area